


ECU



	BAT	ST	IG	E	LO
OFF			○	○	
ON	○				○
ST	○	○			○

